



Symbol	a [mm]	b [mm]	c [mm]	d [mm]	e [mm]	f [mm]
ZWOD40	40	40	25	5	10	5
ZWOD50	50	50	30	6	12	6
ZWOD60	60	60	37	8	15	8